

5/019/072

POGM RECEIVED
4-10-96



A. Part of the access road on which Western Clay Company's contractor is applying shale as road base in T.24S., R.7E., Section 15 under notice, UTU-73779. 4-2-96.



B.. Second realignment on Western Clay Company's access road to their gypsum mine in T.24S., R.7E., Section 15, notice UTU-73779. 4-2-96.

5/015/072

DOGM RECEIVED
4-10-96



n C. Culvert for the first wash crossing on the access road, Western Clay Company, Notice UTU-73779, in T.24S., R.7E., Section 23. 4-2-96.



D. Entrance to the Western Clay Company gypsum mine in T.24S., R.7E., Section 23, notice, UTU-73779. 4-2-96.

5/015/072
DOGM RECEIVED
4-10-96



E. Track-mounted backhoe located at the western end of the mine in T.24S., R.7E., Section 23, notice, UTU-73779. 4-2-96.



F. Grader removing shale overburden in T.24S., R.7E., Section 23, the western portion of the mine, notice UTU-73779. 4-2-96.

S/OIS/072
DOGM RECEIVED
4-10-96



F. Eastern end of the surface disturbance in the gypsum mine, Western Clay Company notice, UTU-73779 in T.24S., R.7E., Section 23. 4-2-96.



G. Looking west over the western part of the mine and the access road in T.24S., R.7E., Section 23, notice UTU-73779. 4-2-96.



H. Side view of the access road just west of the gypsum mine,
Western Clay Company notice UTU-73779 in T.24S., R.7E.,
Section 23. 4-2-96.